



U.S. Department
of Transportation

**Pipeline and Hazardous
Materials Safety Administration**

East Building, PHH-32
1200 New Jersey Avenue, Southeast
Washington, D.C. 20590

05/07/2015

Mr. Elen Bernabe
Operations Manager
South Florida Hydrotesting Corporation
7815 West 2 Court Bay # 7
Hialeah, FL 33014 United States

Expiration Date:05-07-2020

Dear Mr. Bernabe:

The Office of Hazardous Materials Special Permits and Approvals has reviewed your application for approval as a cylinder requalification facility under Section 107.805 of Title 49 Code of Federal Regulations (49 CFR). At the recommendation of Steigerwalt Associates, Inc., this office reissues requalifier identification number (RIN) **H957** to your facility at 7815 West 2 Court Bay # 7, Hialeah, FL for requalifying cylinders by the "**ultrasonic**" test method, in accordance with Special Permit(s) "SP14149 and SP14206", hereafter referred to as 'the Special Permit(s)'. The RIN applies to this location only and is valid until the posted expiration date above subject to the continuation of the special permit(s) or until terminated by the Associate Administrator for Hazardous Materials Safety.

In addition to the requirements of the special permit(s) and the relevant provisions in Sections 180.205 through 180.215 of 49 CFR, the following conditions must be met:

1. You must notify this office of any change in facility name, address, ownership, management, equipment, or testing personnel within twenty days of the change.
2. Testing must be performed by a tester qualified under the special permit(s) and observed by the authorized inspector, or qualified under the special permit(s) and added to your file by addition under condition number one (1) above.
3. A copy of this approval must be maintained adjacent to the testing unit.
4. All cylinders rejected under the special permit(s) must follow the requirements of the special permit regarding rejected or condemned cylinders.
5. Copy of your application, current copy of the special permit(s), and all supporting documentation must be retained and made available to DOT upon request.
6. Each "Hazmat employee", as defined in Section 171.8, who performs a function subject to this approval, must receive appropriate training in accordance with Section 172.700 through 172.704.

Tracking No: 2015050080

Page 1 of 2

7. If required by the applicable Special Permit, the holder of this approval must be listed as an approved agent/tester, under the applicable DOT Special Permit(s), prior to testing cylinders under the authority of this approval.
8. All correspondence must include the requalifier identification number (RIN).

Duane M. Cassidy

For Dr. Magdy El-Sibaie
Associate Administrator for Hazardous Materials Safety